CABLING123
A WAVE2WAVE COMPANY


SC Pushable Connector Installation Instruction




1. Pushable connector with Pulling cap.




2. Rotate Pulling cap 90 degrees and then remove it.




3. Slide boot over pushable connector.



4. Remove the dust cap, align the ontch on housing with the two dot on the body of the connector.



5. Insert the housing until it snaps into place.



6. Re-fit the dust cap, align the ontch on coupling with the ontch on housing.



7. Slide the coupling over the housing until it snaps into place, push the boot into the body of the connector.



8. Finished SC pushable connector.