INSTALLATION INSTRUCTIONS

OUTDOOR ARMORED SC PUSHABLE CONNECTOR

Field-installable SC connector for armored outdoor drop cable. Follow steps in order — do not skip the dot/notch alignment in step 4.

PULLING CAP	BOOT	HOUSING	COUPLING
protective tip	strain relief	two-dot index	outer collar

1



PULLING CAP

Pushable connector with pulling cap

2



ROTATE & REMOVE

Rotate the Pulling Cap 90° andpull it straight off.

3



SLIDE ON BOOT

Slide the Boot over the connector body toward the cable

4



ALIGN DOTS & NOTCH

Remove the dust cap. Align the notch on housing with the two dots on theb ody of the connector

5



SNAP HOUSING

Insert the housing until it snaps into place - the dot must remain visible


6



STAGE COUPLING

Re-fit the dust cap, align the notch on the coupling with the notch on the housing

7



ENGAGE COUPLING

Slide coupling over housing until it snaps into place. Push the boot into the body of the connector

8



RE-FIT DUST CAP

Align the notch on the coupling with the notch on the housing. Re-fit the dust cap. Finished